

Natural Wood Lye

Product properties

Lye for light-coloured wood, indoors. Gives a uniform, white-coloured and lye-treated appearance with a clear, visible wood structure. Minimises the natural yellowing of the wood to keep it light. The colour shade may vary depending on the type of wood.

- **White-coloured appearance**
- **Visible wood structure**
- **Minimises the natural yellowing of the wood**



Labelling



Product use

Use on new, untreated or freshly sanded wood. For example, floors, furniture or tabletops where a lye-treated appearance is desired. Also suitable for oak.

Substrate

Must be clean, dry, firm and suitable for surface treatment.

Treatment

Residues of varnish and paint must be completely removed to clean wood by sanding. Clean with Natural Wood Cleaner.

Sand the surface slightly with fine sandpaper.

Vacuum and wipe dry with a hard-wrung cloth.

Lye treatment alone will not protect the wood.

Therefore, the surface must be treated with either Natural Wood Floor Soap or Floor Oil.

When treated with Natural Wood Floor Soap, the surface becomes saturated and easy to clean.

When treated with Natural Wood Floor Oil, the surface becomes more robust and easy to clean.

Application

Shake before and during use.

Use undiluted.

Apply with a brush or roller in an even layer along the length of the wood.

Smooth out overlaps with a brush while the wood is still wet.

Sand when the wood is dry to remove grain and any excess colour.

For a whiter appearance, repeat the treatment when the wood is dry.

Always carry out a test treatment to verify and accept the adhesion and result.

Expected result

Uniform surface for further treatment.

Lye-treated wood should be washed with Natural Wood Cleaner after approx. 1 hour to remove excess pigments from the surface.

Finish with floor soap or floor oil to make the surface dirt- and water-repellent.

To protect the floor, you may want to place felt pads under tables and chairs.

Cleaning and maintenance

Lye-treated surfaces that are treated with Flügger NW Floor Soap are cleaned and maintained with Flügger NW Floor Soap, white or clear.

Lye-treated surfaces that are treated with Flügger NW Floor Oil are cleaned and maintained with Flügger NW Soap Oil, white or clear.

Environmental information

Remove as much paint as possible from tools before cleaning.

Paint and cleaning fluid must not be poured down drains, but collected and disposed of as environmental waste.

Empty and dry packaging should be sorted as plastic.

Storage

Cool, frost free and tightly closed

Protection equipment

Protect skin and eyes from splashes with suitable clothing, gloves and glasses.

Avoid inhalation of spray mist and grinding dust.

Wear suitable protective equipment, see safety data sheet for further information.

Technical Data

Product Type	Impregnation
Density (kgs/l)	1.1
pH	8
Nominal spreading rate (m ² /ltr.)	10
Min. working temp. during application and drying/curing	Min. +5°C
Humidity	Max. humidity 80 % RH.
Recoatable at 20° C, 60 % RH (Hours)	5
Dilution	Do not dilute
Cleaning of Tools etc.	Water
Country of Origin	Denmark

Current TDS Version

December 2024

Replaces TDS Version

April 2024

